

FIG. 1A PRIOR ART






FIG. 1B PRIOR ART

09282840-122204




F I G. 2

702201 * 04023B660



F I G. 3

TO220T-04828660



F I G. 4

002201-04928660




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9A

EVENT	EVENT AT PREVIOUS STAGE	ROUTE IDENTIFICATION CODE
A		O
B	A	O
C	A	O

FIG. 9B




FIG. 10A

EVENT	EVENT AT PREVIOUS STAGE	ROUTE IDENTIFICATION CODE
A	NONE	0
B	A	0
C	A	0
D	B	1
E	C	0
F	C	0

FIG. 10B

2020V.04828650




FIG. 11A

EVENT	PREVIOUS STAGE	ROUTE IDENTIFICATION CODE
A	NONE	O
B	A	O
C	A	O
D	B	1
E	C	O
F	C	O
G1	D	2
G2	E	O
H	F	O

FIG. 11B




FIG. 12A

EVENT	PREVIOUS STAGE	ROUTE IDENTIFICATION CODE
A	NONE	O
B	A	O
C	A	O
D	B	1
E	C	O
F	C	O
G1	D	2
G2	E	O
H	F	O
I1	G1	3
I2	G2	4
I3	H	O
J1	D	5
J2	I1	3
J3	I2	4
J4	I3	O

FIG. 12B




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19

102207 01020660




FIG. 20







FIG. 21



F I G. 22



F I G. 2 3



F I G. 2 4







FIG. 25




F I G. 26




F I G. 27



F I G. 28



F I G. 29



F I G. 30






FIG. 31




F I G. 32

102201-04828650




F I G. 33


095650 04888211



F I G. 34



F I G. 35



F I G. 3 6




FIG. 37